USB Printing for Touch

OPOS Utility:

For USB printing on Touch you need to use OPOS and set a Logical Device Name or LDN. Each manufacturer will have their own OPOS utility for Epos Receipt printers and you need to get the correct OPOS utility for the make and model printer you are using. You can usually download the OPOS utilities from the manufacturer's websites.

In most cases you also need to install the Windows printer driver first.

The example images below are for a Senor GTP250 receipt printer.

Step 1, Install the Windows Driver

Step 2, Install the OPOS utility

Step 3, Open the OPOS utility and add the printer


Step 4, Set the Logical Device Name (LDN)

Step 5, Do a test print from the OPOS utility

Once at this stage when you can do a successful test print from the OPOS utility, close the utility, start Touch and go into the Back-Office settings.

The two settings below need to be set on Touch. The USB Printer Device name must match the Logical Device Name set on the OPOS utility.

USB printers are also supported for Remote Printer and need specific Logical Names Set as below.

USB1 = TOUCHUSB1
USB2 = TOUCHUSB2
USB3 = TOUCHUSB3 and so on.